

# MIFACE Investigation #06MI007

## Subject: Forklift Driver Pinned Under an Overturned Forklift Dies

### Summary

On February 17, 2006, a 46-year-old Hispanic male utility man was killed when he backed an 8,670-pound, propane-powered Toyota Model 426FGCU25 forklift over the edge of a loading dock, which then overturned and landed on him. The dock plate had two standard guardrails on either side with a chain across the dock opening. There were no witnesses to the events prior to the incident or to the incident itself. The decedent was discovered when another employee traveling through the area noticed the forklift's lights shining on the wall and the truck's forks up and against the wall in the truck well. This employee summoned others to the area when he discovered the decedent pinned face down between the concrete floor and the overhead guard. Several employees manually lifted the forklift enough to move the decedent from under it. It is assumed that the forklift was traveling in reverse, because neither the forks nor the mast appeared bent, as would have been the case if he had been traveling forward and drove off of the dock edge. It is unknown if he jumped or was thrown from the operator's seat. 911 was called and paramedics pronounced him dead at the scene.



Figure 1. Forklift on dock floor

### RECOMMENDATIONS

- Employers should install drop-off protection capable of withstanding forklift impact on a loading dock entrance when the dock entrance is near a normal path of travel for a forklift or pedestrian.
- Employers should enforce employee use of the operator restraint provided by the forklift manufacturer (in this case, a seatbelt).
- If the truck is not transporting a load that obstructs forward vision, forklift operators should limit the distance that the truck travels in reverse.

Key Words: Machine, Forklift, Hispanic

## INTRODUCTION

On February 17, 2006, a 46-year-old Hispanic male utility man was killed when he was pinned under an overturned forklift. On February 17, 2006, MIFACE investigators were informed by the Michigan Occupational Safety and Health Administration (MIOSHA) personnel who had received a report on their 24-hour-a-day hotline, that a work-related fatal injury had occurred and the decedent had died on that day. On February 21, 2006, MIFACE interviewed the firm's Human Resource Manager, Assistant Plant Manager and several of the decedent's coworkers, including union officials. During the course of writing this report, the police report, medical examiner's report, and MIOSHA file and citations were reviewed. The decedent's employer granted MIFACE permission to view the incident site and take incident site pictures and pictures of the damaged forklift, which had been placed in storage. Figures 1, 4, 6, and 7 are courtesy of the MIOSHA compliance officer and have been modified to remove identifiers. Figures 2, 3, and 5 were taken at the time of the MIFACE site visit.

The decedent's employer conducted heat treat operations, and manufactured and processed ball bearings for the automotive industry. The firm also assembled small parts. The firm employed approximately 250 people, had a three-shift operation, and had a unionized workforce. Twelve individuals had the same job classification as the decedent, utility man. The decedent was one of approximately 60 people who worked third shift. On the night of the incident, there were two shift foremen and three to four utility persons, in addition to the other third shift workers. The decedent was a temporary employee who was employed full-time as an hourly employee. He had been a utility man for the past five months. A utility person was assigned specified job assignments, such as cleaning bathrooms, emptying dumpsters, etc. The utility person would also have special assignments as determined by the shift foreman. The decedent's job tasks included driving a forklift, but driving a forklift was not his primary responsibility. He had previous experience at another firm operating a forklift. He wore glasses. The decedent's work shift began at 11:00 p.m. and ended at 7:00 a.m. He had worked first shift for the previous five months. He had ended working first shift on a Friday afternoon, and begun working third shift two days later on a Sunday evening. The incident occurred on the fourth day of his third shift work. Fellow employees interviewed stated that the decedent liked working third shift.

The firm had a written health and safety program, including a joint health and safety committee. Up until approximately one and one-half weeks prior to the incident, the occupational health nurse had primary responsibility for the safety program. The nurse maintained training databases, arranged for training videos and facilitated the safety committee. The safety committee met monthly, and the results were shared with upper management. The safety committee supplied upper management with a checklist to "buddy up" with a knowledgeable person to assess health and safety items in a department. Accidents, injuries, and near misses were to be reported to senior management so proactive efforts to prevent a future injury/loss incident could be implemented.

The firm's health and safety policy required safety glasses with eye shields and hearing protection in certain designated areas. Employee health and safety training was conducted on each work shift by the occupational health nurse and the union. Forklift training was conducted for all forklift operators. The decedent had successfully completed both the written and practical tests and was in possession of a valid operator permit.

English was the primary language of the decedent. At the conclusion of the MIOSHA investigation, the firm was issued an Other-than-Serious citation:

- MIOSHA General Industry Safety Standard - Powered Industrial Trucks, Part 21.
  - Rule 2154(6)(f) – Restrictions for glasses were not identified on powered industrial truck operator permits.

The MIOSHA General Industry compliance officer made two safety recommendations to the company:

- Recommended that the firm maintain documentation for daily forklift checks. The company developed the documentation form and it was now in place. NOTE: Part 21 does not require the employer to maintain records of daily checks but only suggests that the sample in the standard is representative of the daily check requirement.
- Recommended that forklifts have rear view mirrors installed. The firm has contracted with a third party to complete the mirror installation.

## INVESTIGATION

The forklift involved in the incident was a propane-powered Toyota Model 426FGCU25 weighing 8,670 pounds. The forklift's rear tires were smooth and the front tires had treads. The forklift had an overhead guard and was equipped with a functional seat belt system (Figure 2, circle). The deceased operated the forklift in all areas of the plant and was familiar with the plant's layout. The forklift controls were not clearly labeled. The assistant plant manager stated that the firm's forklift training included a requirement that seatbelts must be worn when operating a forklift equipped with a seatbelt. Daily forklift safety checks were performed and verbal information passed on for the equipment concerning inspection and maintenance. No documentation was maintained for daily operator checks. Employees stated that forklift maintenance was timely; when a machine was taken out of service, a rental machine was acquired.



Figure 2. Forklift involved in incident

The incident occurred at a loading dock. Standard guardrails were installed six inches away from the edges of the 6-foot wide loading dock plate. The loading dock floor was approximately four feet below the plant floor. Adjacent to the loading dock was an 8-foot-wide overhead door leading to Area #1. On either side of the overhead door were guardrails protecting the entrance to the door (Figures 3 and 4 and Diagram 1). At the time of the incident, the loading dock entrance had a chain across the opening.





Figure 3. Overhead door near loading dock platform



Figure 4. Position of loading dock in relation to overhead (O/H) door



On the day before the incident, Area #1 had a roof leak and water was entering the plant area via the leak. To catch the dripping water, the decedent was directed to take a palletized empty 27-inch wide x 17-inch tall x 28-inch long heavy cardboard box, line it with a plastic bag, and take it to Area #1, mop up the leak, and place the box under the leak. Area #1 also stored other empty similarly sized palletized cardboard boxes. The next evening, the decedent told the supervisor that he had found two additional areas with roof leaks and would place a box with liner in those areas as he had done the night before.

The decedent had taken an authorized work break – several employees had seen him and talked with him in the break room and he appeared alert at that time. After the break, he climbed into the forklift and drove away. Shortly thereafter, a coworker needed an empty



cardboard box for parts. He climbed aboard a forklift and drove to Area #1 to retrieve a box/pallet. He passed by the loading dock but did not see the decedent. Upon returning to his workstation, he noticed the forklift's lights shining on the wall and the truck's forks up and against the wall in the truck well. He stopped and went to the edge of the loading dock and after seeing the decedent's leg, he ran for help. The forklift was still running when he found the decedent.

The decedent was found laying face down on the cement floor with the left rear support of the overhead guard lying across his back. A number of employees returned and one of these coworkers turned the forklift engine off. The coworkers were able to momentarily manually lift the forklift so that someone could pull the decedent from underneath the overhead guard. Preliminary first aid was started and continued until emergency response personnel arrived. Emergency response arrived and declared the decedent deceased at the scene.



Figure 5. Bent dock boarding plate




Figure 6. Straightened chain fastening loop

Investigation of the incident scene noted that there were no skid or brake marks on the plant floor. The decedent was not carrying a load at the time of the incident. It appears that the forklift was driven off the dock while traveling in reverse based upon the position of the truck. Neither the forks nor the mast appeared bent, as would have been the case if he had been traveling forward and drove off of the dock edge. The counterweight attachment bolt sheared, and the counterweight had detached from the machine and was lying to the side. A fresh impact point was noted in the cement of the truck well approximately three and one-half feet from the top of the loading dock. The left rear tire was approximately five and one-half feet from the edge of the loading dock platform.

This distance suggests that the forklift was traveling at a fairly fast rate. The barrier chain across the dock opening was sheared off. The dock boarding plate had a significant bend on the edge and the chain's fastening loop was sticking straight out (Figures 5 and 6).

The forks were facing upward and were leaning against the truck well wall. The forklift fork gouged the wall at a height of approximately 103 inches. A scrape on the wall began approximately 8 feet above the loading dock floor and ended at approximately 44 inches above the floor. It is thought that the scrape was made when trying to lift the forklift from the decedent's back.

The event was unwitnessed. It is unknown what caused the decedent to back off the end of the loading dock, but a likely scenario is that he was driving in reverse at a significant rate of speed. The damaged/bent dock plate and the location of the machine, several feet from the loading dock edge, after falling to the dock floor supports this hypothesis. A less likely hypothesis is that the decedent was moving slowly, and as the forklift's rear wheels came off of the dock edge, he panicked. Forgetting to place the gearshift in forward, he applied the gas in an attempt to



Figure 7. Position of forklift in relation to loading dock platform

move the machine forward. As the forklift was still in reverse, the machine would have traveled off of the loading dock plate. This scenario is less likely because it is unlikely that the forklift would have traveled so far from the edge under this scenario.

It is unknown whether the decedent attempted to jump from the operator's seat as the forklift proceeded over the dock plate to the truck well floor or whether he was thrown from the forklift as it fell.

An employee who worked with the decedent stated that the decedent had difficulty with his peripheral vision as he had to turn his head to align with the center of travel when he drove the forklift. He also stated that he had seen the decedent hit a wall with a hopper while moving it, but there had been no damage or injuries and he did not report the incident to management.

At the conclusion of the MIOSHA investigation, the company reviewed the powered industrial truck permits of all employees who operated a forklift and surveyed the operators to determine if operator restrictions needed to be noted on the permit. The firm

has issued new powered industrial truck operator permits to employees who wear corrective lenses with the permit indicating that glasses must be worn during truck operation.

## **CAUSE OF DEATH**

The cause of death as listed on the death certificate was multiple injuries. Toxicology was negative for alcohol and other screened drugs.

## **RECOMMENDATIONS**

- Employers should install drop-off protection capable of withstanding forklift impact on a loading dock entrance when the dock entrance is near a normal path of travel for a forklift or pedestrian.

A barrier chain was the only device used to protect the loading dock platform. Loading docks that are vacant can create a hazardous situation for dock personnel, material handlers and pedestrians in the area. Providing drop-off protection at the platform by installing a safety barrier that can be manually positioned and removed by a single forklift operator can be a solution for this problem. When the drop-off protection is in position, it can also provide a constant visual safety reminder of the dock area. There are several manufacturers that provide easy-to-use and relatively inexpensive drop-off protection devices to eliminate this hazard and prevent an injury.

- Employers should enforce employee use of the operator restraint provided by the forklift manufacturer (in this case, a seatbelt).

The forklift involved in this incident was equipped with an overhead guard and a seatbelt for operator restraint. The overhead guard was relatively undamaged during the tip-over. If the operator had been restrained with a seatbelt, the severity of the injuries may have been significantly reduced.

As a forklift starts to roll, its initial momentum is slow. Due to the initial slow movement, an operator may think that he or she has time to abandon the forklift in time. But when the forklift's center of gravity passes the wheel line, the slow overturn rapidly accelerates and an operator who is partially off the truck is often pinned or crushed under the overhead guard.

MIOSHA General Industry Safety Standard Part 21, Powered Industrial Truck operator training standard requires employers to train all operators in the capacities of the equipment and attachments and the purpose, use and limitations of controls of the forklift. Employers should train operators of sit-down type forklifts that the overhead guard or another part of the truck can crush them if they jump from the overturning forklift. The overhead guard of the forklift is generally the part that crushes the operator's head or torso after he or she falls or jumps outside of the operator's compartment. The risk of being crushed by the overhead guard or another rigid part of the forklift is greatly

reduced if the operator of a sit-down type forklift remains inside the operator's compartment. The operator of a sit-down type forklift should wear the seatbelt (if equipped) and stay with the truck if lateral or longitudinal tip-over occurs. The operator should be instructed to stay in the operator's compartment (i.e., do not attempt to jump), hold on firmly to the steering wheel, brace your feet, and lean away from the direction of the tip-over or overturn, making sure arms and legs remain within the operating area of the forklift.

National consensus standard ANSI/ITSDF B56.1-2005, Safety Standard for Low Lift and High Lift Trucks, requires manufacturers of counterbalanced, center control high lift trucks that have a sit-down, non-elevating operator to identify the means (operator restraint device or system) that the operator may use to assist in keeping his/her head and torso substantially within the confines of the truck frame and overhead guard if a tipover should occur. The standard also requires operators to wear operator restraint systems when provided by the forklift manufacturer. Many forklift manufacturers install seat belts in the forklift truck as a component part of an operator restraint system that is designed to reduce the incidence and severity of injuries to the operator in the event of a tip-over accident. Since 1992, forklift manufacturers have been required to equip new sit-down type forklifts with operator restraint systems. Many forklift manufacturers offer restraint systems that can be retrofitted on older forklifts.

NOTE: In 2005 the copyright of the ASME B56.1-2004 was obtained by ITSDF (Industrial Truck Standards Development Foundation) in Washington, DC. The standard number was changed to ANSI/ITSDF B56.1-2005 (Reaffirmation of AMSE B56.1-2004 after references to ASME were changed to ITSDF). This standard can be downloaded for free from the ITSDF website at: <http://www.itsdf.org/default.asp>.

- If the truck is not transporting a load that obstructs forward vision, forklift operators should limit the distance that the truck travels in reverse.

Although the decedent was not transporting a load, it is hypothesized that he backed out of the storage area instead of driving forward out of the area. It is unknown if he was looking in the rearward direction of travel, or if he became distracted and was unaware of his proximity to the loading dock. Driving a forklift in reverse (backing up) is a common work practice during truck unloading and after a transported load delivery. When driving the forklift from one point to another, it is preferable for a forklift operator to drive the forklift in a forward direction of travel rather than in reverse unless transporting a load up a slope or line of site conditions caused by the load prohibits safe forward travel.

## REFERENCES:

MIOSHA standards cited in this report may be found at and downloaded from the MIOSHA, Michigan Department of Labor and Economic Growth (DLEG) website at: [www.michigan.gov/mioshastandards](http://www.michigan.gov/mioshastandards). MIOSHA standards are available for a fee by writing to: Michigan Department of Labor and Economic Growth, MIOSHA Standards Section, P.O. Box 30643, Lansing, Michigan 48909-8143 or calling (517) 322-1845.



The MIOSHA Consultation Education and Training (CET) Division offers many health and safety services to both public and private sector employers in Michigan. For free help in establishing or improving your safety program, contact: MIOSHA Consultation Education and Training Division, 7150 Harris Drive P.O. Box 30643, Lansing, MI 48909-8143. Phone: (517) 322-1809. Fax: (517) 322-1374

Internet Address: [www.michigan.gov/cis/0,1607,7-154-11407\\_15317---,00.html](http://www.michigan.gov/cis/0,1607,7-154-11407_15317---,00.html).

- MIOSHA General Industry Safety Standard Part 21, Powered Industrial Trucks.
- New Jersey FACE Investigation Report #02-NJ-081: Forklift Operator Dies After Backing His Forklift Off A Loading Dock
- Washington State FACE: SHARP Report #71-32-2005. Operator Killed When Construction Forklift Rolls Over
- NIOSH Publication No. 2001-109: NIOSH Alert: Preventing Injuries and Deaths of Workers Who Operate or Work Near Forklifts. Internet Address: <http://www.cdc.gov/niosh/2001-109.html#6>
- NIOSH in-house FACE Report #2000-09: Sixteen-Year-Old Laborer At a Building Supply Center Crushed by Forklift That Tipped Over – Ohio. Internet Address: <http://www.cdc.gov/niosh/face/In-house/full200009.html>
- ANSI/ITSDF B56.1-2005 [2005] Industrial Truck Standards Development Foundation (ITSDF). Internet Address: <http://www.itsdf.org/default.asp>.
- MIOSHA CET Onsite Consultation Abatement Method for Powered Industrial Trucks (Publication OSC- 6065 (Rev.4/05)). Internet Address: [http://www.michigan.gov/documents/cis\\_wsh\\_osc6065\\_125820\\_7.doc](http://www.michigan.gov/documents/cis_wsh_osc6065_125820_7.doc).
- MIOSHA CET pMIOSHA CET publications to assist you in your powered industrial truck operator training program may be found at: [http://www.michigan.gov/cis/0,1607,7-154-11407\\_30453-93831--,00.html](http://www.michigan.gov/cis/0,1607,7-154-11407_30453-93831--,00.html). Click on the “Powered Industrial Trucks (Forklifts)” link or scroll down the page until you find the appropriate section.

MIFACE (Michigan Fatality Assessment and Control Evaluation), Michigan State University (MSU) Occupational & Environmental Medicine, 117 West Fee Hall, East Lansing, Michigan 48824-1315. This information is for educational purposes only. This MIFACE report becomes public property upon publication and may be printed verbatim with credit to MSU. Reprinting cannot be used to endorse or advertise a commercial product or company. All rights reserved. MSU is an affirmative-action, equal opportunity employer.

5/17/07

# MIFACE

## Investigation Report #06 MI 007

### Evaluation

To improve the quality of the MIFACE program and our investigation reports, we would like to ask you a few questions about this report:

Please rate the report using a scale of:

|                  |             |             |             |
|------------------|-------------|-------------|-------------|
| <b>Excellent</b> | <b>Good</b> | <b>Fair</b> | <b>Poor</b> |
| 1                | 2           | 3           | 4           |

***What was your general impression of this MIFACE investigation report?***

|                  |             |             |             |
|------------------|-------------|-------------|-------------|
| <b>Excellent</b> | <b>Good</b> | <b>Fair</b> | <b>Poor</b> |
| 1                | 2           | 3           | 4           |

|                                 |                  |             |             |             |
|---------------------------------|------------------|-------------|-------------|-------------|
| <b><i>Was the report...</i></b> | <b>Excellent</b> | <b>Good</b> | <b>Fair</b> | <b>Poor</b> |
| Objective?                      | 1                | 2           | 3           | 4           |
| Clearly written?                | 1                | 2           | 3           | 4           |
| Useful?                         | 1                | 2           | 3           | 4           |

|                                            |                  |             |             |             |
|--------------------------------------------|------------------|-------------|-------------|-------------|
| <b><i>Were the recommendations ...</i></b> | <b>Excellent</b> | <b>Good</b> | <b>Fair</b> | <b>Poor</b> |
| Clearly written?                           | 1                | 2           | 3           | 4           |
| Practical?                                 | 1                | 2           | 3           | 4           |
| Useful?                                    | 1                | 2           | 3           | 4           |

***How will you use this report? (Check all that apply)***

- ☐ Distribute to employees
- ☐ Post on bulletin board
- ☐ Use in employee training
- ☐ File for future reference
- ☐ Will not use it
- ☐ Other (specify) \_\_\_\_\_

**Thank You!**

**Please Return To:**

MIFACE  
Michigan State University  
117 West Fee Hall  
East Lansing, MI 48824  
FAX: 517-432-3606

If you would like to receive e-mail notifications of future MIFACE work-related fatality investigation reports, please complete the information below:

Name: \_\_\_\_\_

e-mail address: \_\_\_\_\_

**Comments:**

\_\_\_\_\_  
\_\_\_\_\_