




Handling a Temperature Excursion in Your Vaccine Storage Unit

Any temperature reading outside ranges recommended in the manufacturers' package inserts is considered a temperature excursion. Identify temperature excursions quickly and take immediate action to correct them. This can prevent vaccine waste and the potential need to revaccinate patients.



MANUFACTURER CONTACT INFORMATION FOR EXCURSIONS

AstraZeneca: 800-236-9933

Bavarian Nordic: 844-422-8274

CSL Sequris: 855-358-8966

Dynavax: 844-375-4728

Emergent Biosolutions: 888-483-9053

GSK: 877-356-8368

[Stability calculator](#)

Merck: 800-672-6372

[Stability calculator](#)

Moderna: 866-663-3762

[Stability calculator](#)

Novavax: 844-668-2829

Pfizer: 800-438-1985

[Stability calculator](#)

Sanofi: 800-633-1610

[Stability calculator](#)

Valneva: 844-349-4276