


SUPPLEMENTAL FIGURE: Cyanotoxin Detection Levels and Sampling Locations for Lake Water Monitoring and Tap Water Testing for Homes with Near-shore Wells or Lake Water Intake Systems - Clear Lake, California, June-November 2021



Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), and the GIS User Community